
Ball Driver Replacemnt Tip 1.5mm



Ball Driver Replacemnt Tip 1.5mm

Rating: Not Rated Yet **Price**

Price with discount \$2.90

Salesprice with discount

Sales price \$2.90

Sales price without tax \$2.90

Discount

Tax amount

Ask a question about this product

1 / 2

Description

This is the 1.5mm Ball Driver Replacement Tip for DTXR0293.

FEATURES: Hardened steel construction

INCLUDES: One replacement tip

REQUIRES: DTXR0293 ball driver tjt 102103

BOX DIMENSIONS: 2.00" W. X .25" H. X 3.38" L. BOX WEIGHT: .02 LBS.

2 / 2